This Page Is Inserted by IFW Operations and is not a part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images may include (but are not limited to):

- BLACK BORDERS
- TEXT CUT OFF AT TOP, BOTTOM OR SIDES
- FADED TEXT
- ILLEGIBLE TEXT
- SKEWED/SLANTED IMAGES
- COLORED PHOTOS
- BLACK OR VERY BLACK AND WHITE DARK PHOTOS
- GRAY SCALE DOCUMENTS

IMAGES ARE BEST AVAILABLE COPY.

As rescanning documents will not correct images, please do not report the images to the Image Problem Mailbox.




FIGURE 1

7	\	Ŧ

	57 -2	BWWFG Line 26 Underbody 2 2 Originating Group	A Choose A Date	February 2003	2 3 4 5 6 7 8	CoC Methods & Standards Help 10 11 12 13 14 15 15 15 15 15 15 15	
22 New LOP Item Use this form to create a new LOP Item.		n 🖾 - 24	SARPLE - NEW LOP ITER	- 6%	Uescription	Medium So BIW Planning Priority Responsible Group	Submit Reserv
2				4	2		Submitted I OD Information

FIGURE 2

Please retain a copy of this information for your racords. The LOP Tracking Number below has been assigned to your LOP submission.

Originating Stab Group: Bity mr congluenting Sub Group: Underbody
Medium

BIW MFG Line II Oubti, Marwan

Orlginator: Model:

Responsible Group: BIW Planning Responsible Sub Group: CoC Methods & Standards


2/6/2003 10:27:47 AM 2/1/2003

LOP Tracking Number: 6013

Date Submitted:

Due Date:

SAMPLE - NEW LOP ITEM LOP Description:



Back to LOP Home

LOP Item Transfer

72 18013	VY	46	
Trooting Ali.	+		
A. S.	Date Initiated	Due Date	
	2/6/2003 10:27:47 AM	2/7/2003	
1	Originator — 4.5	Originating Group -47	Orlg. Sub Group - 48
4º E53	Oubti, Marwan	BIW MFG Line II	
Description			force of the second
SAMPLE - NEW LOP ITEM			
	,	53	بر 4
глоту		Responsible Group	Resp. Sub Group
Medium (BW Planning	CoC Methods & Standards
Enter transfer information below for LOP item number:6013	r LOP tem number:6013		-
Transfer To Responsible Group:	Responsible Sub Group:		
		10 2	
737			
Activity			
emigns.			
	1		
4	TIGORE 4	Fr 4	٠.





FIGURE 5



ES3 High / Closed

Cleassens, PeterSimmons, Timothy 9,000,000 I can I select the month or the year for the date LOP Admin 9,000,0000 for this new flem, nor can I select the month ...

The LOP approval and assignment procedure needs to E53 be reviewed. New LOP's should be reviewed by a gr... High / Closed

All air cleaners in Zone 3 of the bodyshop need to be serviced. We have a tot of problems with them ...

5/24/2002 6/17/2002

Allen, Bill Dawkins, Howard

4747 5/20/2022

7/17/2002 7/17/2002

Qubti, Marwan Adama, Herman LOP Admin BIW ES3 Facelift

4733 5729/2002

FIGURE 6

5585 975/2002

LOP Admin BIW Planning

Priority / Status

thry, asks sere you selv






FIGURE 7

136




FIGURE 8

| | Add, Modify, Delete Associate Information

Use this form to add, modify or delete a user account.

Reliesh Associate Only enter fields to be modified, blank fields will be defaulted to original data.

Original Associate* NT Logon Address Email

Modified

FIGURE 9

Administration

You may access the following administration tools.

Add, Modify, Delete Associate Account Information.

Add, Remove Lead Coordinators.

Reporting

Overview LOP users.

Overview Lead Coordinators,




FIGURE 10




FIGURE 11

